


# Retail Food Inspection Report

Telephone (812) 948-4726

<b>Establishment Name</b> SWANKY FRANKS		<b>Telephone Number</b>  Est  Own		<b>Date of Inspection</b>  02/02/2022		<b>ID#</b>																									
<b>Address</b> 4865 OLD VINCENNES, FLOYDS KNOBS IN 47119																															
<b>Owner</b> SEAN SCALF		<b>Purpose</b> <input type="checkbox"/> Routine <input type="checkbox"/> Follow-up <input type="checkbox"/> Complaint <input checked="" type="checkbox"/> Pre-Operational <input type="checkbox"/> Temporary <input type="checkbox"/> HACCP <input type="checkbox"/> Other (list)		<b>Follow Up</b>		<b>Released</b> 02/12/2022																									
<b>Owner's Address</b> ,				<b>Menu Type</b>  1 <input type="checkbox"/> 2 <input checked="" type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5 <input type="checkbox"/>																											
<b>Person in Charge</b> AL PAPSODERO																															
<b>Responsible Person's Email</b>																															
<b>Certified Food Handler</b> IRIE ABREU																															
CRITICAL ITEMS ARE IDENTIFIED IN THE CHECKLIST AND NARRATIVE COLUMNS MARKED "C" VIOLATION(S) REPEATED FROM PREVIOUS INSPECTIONS ARE DENOTED IN THE "SUMMARY OF VIOLATIONS" AND IN THE NARRAIVE COLUMN MARKED AS "R"																															
<table border="1"> <thead> <tr> <th>Section #</th> <th>C</th> <th>NC</th> <th>R</th> <th>Narrative</th> <th>To Be Corrected</th> </tr> </thead> <tbody> <tr> <td>430</td> <td></td> <td>X</td> <td></td> <td>Observed downspout discharging water onto the roof of storage shed.</td> <td>2 weeks</td> </tr> <tr> <td>411</td> <td></td> <td>X</td> <td></td> <td>Measured lighting above 3 comp at waist level at 5 footcandles. 70 ftc minimum for areas of warewash. Install additional lighting.</td> <td>Before opening</td> </tr> <tr> <td>433</td> <td></td> <td>X</td> <td></td> <td>Observed no method for hanging mops to dry.</td> <td>before opening</td> </tr> </tbody> </table>								Section #	C	NC	R	Narrative	To Be Corrected	430		X		Observed downspout discharging water onto the roof of storage shed.	2 weeks	411		X		Measured lighting above 3 comp at waist level at 5 footcandles. 70 ftc minimum for areas of warewash. Install additional lighting.	Before opening	433		X		Observed no method for hanging mops to dry.	before opening
Section #	C	NC	R	Narrative	To Be Corrected																										
430		X		Observed downspout discharging water onto the roof of storage shed.	2 weeks																										
411		X		Measured lighting above 3 comp at waist level at 5 footcandles. 70 ftc minimum for areas of warewash. Install additional lighting.	Before opening																										
433		X		Observed no method for hanging mops to dry.	before opening																										
<b>Summary of Violations</b> C <u>0</u> NC <u>3</u> R <u>0</u>																															
Received by (name and title printed):				Inspected by (name and title printed): Thomas Snider CFS																											
Received by (signature):				Inspected by (signature): 																											
cc:		cc:			cc:																										